

AZ2514E spin curve

recie:

Spining: xxx rpm; 1000rpm/s, 60sec Bake: 60sec@90C.

Speed, rpm	Average, nm					
1000	2897,05		2949,31	2926,72	2893,25	2916,5825
2000	2022,5	1994,34	1997,48	1987,87	1888,13	1978,064
3000	1622,68	1613,13	1609,42		1651,53	1624,19
4000	1417,34	1417,17	1423,63	1440,41	1448,24	1429,358
5000	1409,29	1302,64	1329,39	1317,72	1307,44	1333,296
6000	1218,16	1264,36	1226,28	1226,93	1238,87	1234,92
7000	1220,29	1198,24	1199,42	1201,51	1201,68	1204,228

